

ID	Due Date/ Follow-up	Description	Assigned To / Contact	Estimate
Open				
Misc.				
599	08/09/2022	1st floor fire door north - doesn't latch	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00
		08/02/2022	3765 - 1st floor fire door north - doesn't latch - closer replaced a couple of weeks ago	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
600	08/09/2022	3765 - 2nd floor fire door north - doesn't latch	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00
		08/02/2022	3765 - 2nd floor fire door north - doesn't latch	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
601	08/09/2022	3765 - garage - storage locker #201 - door doesn't close.	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00
		08/02/2022	3765 - garage - storage locker #201 - door doesn't close	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
602	08/09/2022	3755 - entrance lobby - water mark on ceiling tiles needs to be investigated	CM Robinson Contracting, Inc. Patricia Lau	
			3755 Hartsock Lane #207 Colorado Springs CO, 80917 patriciajl@mac.com;pjl80917@gmail.com	\$0.00
		08/02/2022	3755 - entrance lobby - water mark on ceiling tiles needs to be investigated	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Heidi Torkashvand - To : Patricia Lau.	
603	08/09/2022	3765 garage - storage locker #205 -Door problem	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00

Work Order List
 Hartsock Village CHOA
 Status - Multiplied Selected

Date: 8/14/2022
 Time: 3:46 pm
 Page: 2

ID	Due Date/ Follow-up	Description	Assigned To / Contact	Estimate
		08/02/2022	3765 garage - storage locker #205 - Door problem	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
604	08/09/2022	3765 garage - Sump Pump room - Door problem	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00
		08/02/2022	3765 garage - Sump Pump room - Door problem	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
605	08/09/2022	3765 1st floor community room - one of the closet doors is scrapping the carpet	CM Robinson Contracting, Inc. Robert & Phyllis Reder	
			3765 Hartsock Lane #204 Colorado Springs CO, 80917 RReder46@aol.com (630) 965-5617	\$0.00
		08/02/2022	3765 1st floor community room - one of the closet doors is scrapping the carpet	
		08/02/2022	Email to : chris@cmrobinsoncontracting.com Reason :Thank you Work order report attached	
		08/02/2022	Work Location Changed From : Clifton & Sheila Black - To : Robert & Phyllis Reder.	
			Misc. Count:	7
			Open Count:	7
			Hartsock Village CHOA Count:	7
			Estimate Total:	\$0.00